- WAC 246-236-083 Reports. (1) In addition to the reporting requirements in chapters 246-220 through 246-254 WAC, the licensee shall report the following events if not reported under chapters 246-220 through 246-254 WAC:
  - (a) Source stuck in an unshielded position.
  - (b) Any fire or explosion in a radiation room.
  - (c) Damage to the source racks.
- (d) Failure of the cable or drive mechanism used to move the source racks.
  - (e) Inoperability of the access control system.
  - (f) Detection of radiation source by the product exit monitor.
- (g) Detection of radioactive contamination attributable to licensed radioactive material.
  - (h) Structural damage to the pool liner or walls.
  - (i) Abnormal water loss or leakage from the source storage pool.
- (j) Pool water conductivity exceeding one hundred microsiemens per centimeter.
- (2) The report must include a telephone report within twenty-four hours as described in WAC 246-221-250, and a written report within thirty days as described in WAC 246-221-250.

[Statutory Authority: RCW 70.98.050, 70.98.110 and 58 F.R. 7728, 76 F.R. 56963, 77 F.R. 39906, 80 F.R. 54234. WSR 18-15-017, § 246-236-083, filed 7/9/18, effective 8/9/18.]