WAC 296-301-205 Acid carboys. Carboys must be provided with inclinators, or the acid must be withdrawn from the carboys by means of pumping without pressure in the carboy, or by means of hand operated siphons.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-301-205, filed 9/5/17, effective 10/6/17; Order 74-19, § 296-301-205, filed 5/6/74.]