- WAC 296-104-502 Repairs—What is the standard for nonnuclear repairs and alterations? The standard for repairs/alterations is:
- (1) National Board Inspection Code ($\overline{\text{NBIC}}$), current edition Part 3, excluding Section 6, Supplements 1, 5, 6, and 7 which may be used as nonmandatory guidelines.
- (2) The standard for repair of historical boilers or riveted construction preserved, restored, or maintained for hobby or demonstration use, shall be Part 3, Section 6, Supplement 2 of the National Board Inspection Code (NBIC) current edition.

[Statutory Authority: Chapter 70.79 RCW. WSR 18-23-092, § 296-104-502, filed 11/20/18, effective 1/1/19; WSR 18-01-113, § 296-104-502, filed 12/19/17, effective 1/31/18; WSR 14-13-087, § 296-104-502, filed 6/17/14, effective 8/1/14. Statutory Authority: RCW 70.79.030, 70.79.040, 70.79.150, 70.79.290, 70.79.330, and 70.79.350. WSR 08-24-072, § 296-104-502, filed 12/1/08, effective 1/1/07. Statutory Authority: Chapter 70.79 RCW. WSR 04-21-069, § 296-104-502, filed 10/19/04, effective 1/1/05. Statutory Authority: RCW 70.79.030, 70.79.040, 70.79.150, 70.79.290, 70.79.330, 70.79.350, and chapter 70.79 RCW. WSR 02-23-036, § 296-104-502, filed 11/30/01, effective 1/14/02; WSR 01-24-061, § 296-104-502, filed 11/30/01, effective 1/13/00. Statutory Authority: RCW 70.79.030, 70.79 RCW. WSR 00-21-024, § 296-104-502, filed 10/10/00, effective 11/13/00. Statutory Authority: RCW 70.79.030 and 70.79.040 and chapter 11/13/00. Statutory Authority: RCW 10.79.030 and 10.79.040. WSR 10.79.040. Statutory Authority: RCW 10.79.030 and 10.79.040. WSR 10.79.040. Statutory Authority: RCW 10.79.030 and 10.79.040. WSR 10.79.040. WSR 10.79.040. WSR 10.79.040. Statutory Authority: RCW 10.79.030 and 10.79.040. WSR 10.79.040. WSR