- WAC 296-807-15050 Inspect and maintain tools properly. (1) You must make sure any tool that is not in proper working condition is:
 - (a) Immediately removed from service;
 - (b) Tagged;
- (c) Properly repaired as specified in the manufacturer's instructions before being used again.
- (2) You must regularly service the tool and inspect it for worn or damaged parts at intervals recommended by the tool manufacturer.
- (3) You must replace worn or damaged parts before the tool is used. This must be done:
 - (a) By a qualified person;
 - (b) Using only parts supplied by the tool manufacturer.
 - (4) You must keep a written record of inspection dates.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-15050, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-15050, filed 4/4/03, effective 8/1/03.]