- WAC 296-807-17015 Lift the load safely. (1) You must place a block between the load cap and the load if the load could slip off the jack.
- (2) You must secure the load from falling or slipping immediately after it is raised by one or more of the following:
  - (a) Cribbing;
  - (b) Blocking;
  - (c) Some other equally effective method.
- (3) You must make sure you do not exceed the limit of travel of the jack.

Note:

The limit of travel can be determined by one or more of the following:

- 1. A positive stop;
- 2. A stop indicator;
- 3. Some other equally effective method.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-17015, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-17015, filed 4/4/03, effective 8/1/03.]