

WAC 296-806-20008 Make sure operating controls meet these requirements.

EXEMPTION: This rule does not apply to constant pressure controls used only for setup.

- (1) You must make sure each machine has a control that both:
 - (a) Stops the machine; and
 - (b) Can be reached by the operator without leaving the operator's position.
- (2) You must make sure the operator can easily reach all machine controls without reaching into a hazard area of the machine.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-20008, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-20008, filed 6/29/04, effective 1/1/05.]