WAC 296-806-30002 Fit arbors and mandrels to the machine. (1) You must make sure that arbors and mandrels:

(a) Have firm and secure bearing.

(b) Are free from play.

(2) You must only place or mount attachments on a machine arbor that have been accurately machined to the correct size and shape.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-30002, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-30002, filed 6/29/04, effective 1/1/05.]