WAC 296-806-44502 Safeguard ironworkers point of operation. You must safeguard the different operating stations on ironworkers according to requirements for all machines, safeguarding methods, WAC 296-806-20042 through 296-806-20058.

**EXEMPTION:** If the point-of-operation opening is one-fourth inch or less, safeguarding is not required.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-44502, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-44502, filed 6/29/04, effective 1/1/05.]