- WAC 296-807-15020 Make sure tools and containers are properly labeled. (1) You must make sure tools are properly labeled.
- (2) You must make sure each tool has a readable, permanent label that shows the manufacturer's:
  - (a) Model number.
  - (b) Unique serial number.
- (3) You must make sure there is a durable warning label on each tool that:
- (a) Reads "WARNING FOR USE ONLY BY QUALIFIED OPERATORS ACCORDING TO MANUFACTURER'S INSTRUCTION MANUAL"; or
  - (b) Uses words with the same meaning.
- (4) You must make sure the tool storage container has these labels:
- (a) "POWDER ACTUATED TOOL" on the outside of the container in an easily seen position.
- (b) "WARNING POWDER ACTUATED TOOL. TO BE USED ONLY BY A QUALIFIED OPERATOR AND KEPT UNDER LOCK AND KEY WHEN NOT IN USE" on the inside cover.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-15020, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-15020, filed 4/4/03, effective 8/1/03.]