

**WAC 296-301-070 Silver and ribbon lappers (cotton).** Cover guard. An interlocking cover guard must be installed over the large calender drums and the lap spool, designed to prevent the operator from coming in contact with the nip.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-301-070, filed 9/5/17, effective 10/6/17; Order 74-19, § 296-301-070, filed 5/6/74.]