

WAC 296-307-45540 Control ignition sources.

You must:

- (1) Make sure the vapor areas and adjacent areas do not have any:
- Open flames
 - Spark producing devices
 - Heated surfaces hot enough to ignite vapors.
- (2) Use explosion-proof wiring and equipment in the vapor area.

Reference: Electrical wiring and equipment has to meet the requirements of the applicable hazardous (classified) location. See Hazardous (classified) locations, WAC 296-307-37209.

You must:

- (3) Prohibit smoking in any vapor area:
- Post an easily seen "NO SMOKING" sign near each dip tank.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 03-10-068, § 296-307-45540, filed 5/6/03, effective 8/1/03.]