

WAC 296-307-45565 Make sure conveyor systems are safe.

You must:

- Make sure the conveyor system shuts down automatically if:
 - The ventilation system fails to maintain adequate ventilation

OR

- There is a fire.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 03-10-068, § 296-307-45565, filed 5/6/03, effective 8/1/03.]