

WAC 296-835-12065 Make sure conveyor systems are safe. You must make sure the conveyor system shuts down automatically if:

- (1) The ventilation system fails to maintain adequate ventilation; or
- (2) There is a fire.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-835-12065, filed 9/5/17, effective 10/6/17. Statutory Authority: RCW 49.17.010, [49.17].040, and [49.17].050. WSR 02-15-102, § 296-835-12065, filed 7/17/02, effective 10/1/02.]