

**WAC 296-307-45565 Make sure conveyor systems are safe.** The employer must make sure the conveyor system shuts down automatically if:  
(1) The ventilation system fails to maintain adequate ventilation;

**OR**

(2) There is a fire.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 20-21-091, § 296-307-45565, filed 10/20/20, effective 11/20/20; WSR 03-10-068, § 296-307-45565, filed 5/6/03, effective 8/1/03.]