

WAC 296-806-42050 Provide a detector for mobile conveyors. You must provide a detector to stop conveyor movement when the operation creates a danger of running into a stockpile or other obstacle.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-42050, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-42050, filed 6/29/04, effective 1/1/05.]