

WAC 16-675-035 What condition must your weights and measures standards be in when they are submitted to the laboratory for testing or calibration? Weights and measures standards submitted to the laboratory for tolerance testing or calibration must be in a physical condition that allows the laboratory to perform the requested service.

[Statutory Authority: Chapters 19.94 and 34.05 RCW. WSR 04-23-043, § 16-675-035, filed 11/10/04, effective 12/11/04.]