

WAC 296-36-075 General operating requirements—Identification badge. Every compressed air worker employed in the work shall wear an identification badge furnished by the employer both on and off the job. The badge shall be of durable plastic designed to be worn next to the body. The badge shall state that the wearer is employed as a compressed air worker, shall bear the address and telephone number of the medical lock, and shall contain instructions that in case of an emergency of unknown or doubtful cause or illness, the wearer shall be rushed to the medical facilities and not to a hospital.

[Rules (Part III J), filed 12/28/62; § 24, Rule 2412, filed 3/23/60.]