

WAC 296-803-50025 Protect employees from the hazards of stored and residual energy. (1) You must make sure all potentially hazardous stored and residual energy is relieved, disconnected, restrained, or otherwise rendered safe after the lockout or tagout devices have been put on the energy-isolating devices.

(2) You must continue to verify the isolation of machines and equipment that could reaccumulate stored energy to a hazardous level until:

- (a) Service or maintenance is completed; or
- (b) The possibility of reaccumulating hazardous energy does not exist.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-50025, filed 9/5/17, effective 10/6/17; WSR 04-15-105, § 296-803-50025, filed 7/20/04, effective 11/1/04.]