

**WAC 296-806-450 Lathes.**

**Summary**

In addition to the requirements in this section, you need to refer to the following sections of this chapter in order to fully protect your employees from machine hazards:

Requirements for all machines, WAC 296-806-200 and 296-806-300.

This section applies to the hazards associated with metal and woodworking lathes.

**Your responsibility:**

To protect employees from hazards associated with metal and woodworking lathes.

**METAL LATHES**

| <b>You must meet the requirements...</b>                              | <b>in this section:</b> |
|---|-------------------------|
| Provide shields or guards on metal lathes for chip or coolant hazards | WAC 296-806-45002       |
| Safeguard work-holding devices (chucks)                               | WAC 296-806-45004       |
| Follow these requirements for chip control and handling               | WAC 296-806-45006       |
| Safeguard power-clamping devices                                      | WAC 296-806-45008       |
| Restrain extended workpieces on horizontal lathes                     | WAC 296-806-45010       |

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-450, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-450, filed 6/29/04, effective 1/1/05.]