

WAC 296-36-055 General operating requirements—Temperature in working chamber. Every effort shall be made by the best available means to prevent the wet bulb temperature exceeding 80 degrees F. A wet bulb thermometer, in good working order, shall be provided in every working chamber.

[Rules (Part III F), filed 12/28/62; § 20, Rule 2006, filed 3/23/60.]