

WAC 296-863-300 Inspection, repair, maintenance, and servicing.

Summary:

Your responsibility:

To make sure PITs are kept in safe condition and properly serviced.

References:

1. Appropriate respiratory protection may need to be used when operating PITs. See chapter 296-841 WAC, Respiratory hazards, for more information.
2. Appropriate PPE may need to be worn. See WAC 296-800-160 in the *Safety and Health Core Rules* for more information.

You must meet the requirements...	in this section:
Inspect, Repair and Maintain PITs	
Make sure PITs are in safe working condition	WAC 296-863-30005
Inspect your PITs	WAC 296-863-30010
Meet these requirements when repairing PITs	WAC 296-863-30015
Maintain your PITs properly	WAC 296-863-30020
Service Your PITs	
Service gasoline fueled PITs safely	WAC 296-863-30025
Service liquefied petroleum gas (LPG) fueled PITs safely	WAC 296-863-30030
Make sure battery charging areas are safe	WAC 296-863-30035
Service batteries for electric PITs safely	WAC 296-863-30040

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-863-300, filed 9/5/17, effective 10/6/17; WSR 04-19-051, § 296-863-300, filed 9/14/04, effective 2/1/05.]