

WAC 296-304-040 Welding, cutting and heating—Scope and application. All sections of this chapter which include WAC 296-304-040 in the section number apply to welding, cutting and heating.

You are also required to protect employees from exposure to hexavalent chromium during the stainless steel welding process. See WAC 296-62-08003, Hexavalent chromium for specific criteria.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 06-16-106, § 296-304-040, filed 8/1/06, effective 9/1/06; Order 74-25, § 296-304-040, filed 5/7/74.]