

**WAC 296-803-50060 Coordinate with outside employers servicing or maintaining your machines or equipment.** You must do the following before allowing another employer's personnel to service or maintain machines or equipment if your energy control procedures require they be locked or tagged out:

(1) Inform the outside employer of your lockout or tagout procedures.

(2) Make sure the outside employer informs you of their lockout or tagout procedures.

(3) Make sure you and the outside employer confirm that all employees understand and will follow the restrictions of the other employer's energy control program.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-50060, filed 9/5/17, effective 10/6/17; WSR 04-15-105, § 296-803-50060, filed 7/20/04, effective 11/1/04.]