

WAC 296-870-20035 Heat-producing processes. (1) You must protect the platform members, wire ropes, and lifelines when using a heat-producing process.

(2) You must make sure wire ropes and lifelines which have been contacted by a heat-producing process are considered to be permanently damaged and not used.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-870-20035, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 47.17.060. WSR 06-19-075, § 296-870-20035, filed 9/19/06, effective 1/1/07.]