

**WAC 246-231-180 Inspection, test, and operating status.** (1) The licensee, certificate holder, and applicant for a certificate of compliance shall establish measures to indicate, by the use of markings such as stamps, tags, labels, routing cards, or other suitable means, the status of inspections and tests performed upon individual items of the packaging. These measures must provide for the identification of items that have satisfactorily passed required inspections and tests, where necessary to preclude inadvertent bypassing of the inspections and tests.

(2) The licensee shall establish measures to identify the operating status of components of the packaging, such as tagging valves and switches, to prevent inadvertent operation.

[Statutory Authority: RCW 70.98.050 and 70.98.110. WSR 17-01-034, § 246-231-180, filed 12/12/16, effective 1/12/17. Statutory Authority: RCW 70.98.050. WSR 08-09-093, § 246-231-180, filed 4/18/08, effective 5/19/08.]