- WAC 246-272B-07200 Operator qualifications and responsibilities.
- (1) Owners of LOSS using mechanical treatment or lagoons with design flow greater than 14,500 gpd shall employ one or more operators certified according to chapter 173-230 WAC, Certification of operators of wastewater treatment plants.
- (2) Owners of LOSS with design flow greater than 14,500 gpd not using mechanical treatment or lagoons shall employ one or more operators approved by a local health jurisdiction in Washington state.
- (3) The operator of a LOSS using proprietary treatment shall be qualified to monitor and maintain that LOSS. Examples of a qualified operator include someone who:
- (a) Has experience successfully operating a LOSS with similar technology;
- (b) Is an employee or authorized agent of the treatment component manufacturer;
- (c) Is trained, authorized in writing by, and in good standing with the manufacturer of the proprietary treatment;
- (d) Has education or certification in operating similar technology; or
  - (e) Has other qualifications acceptable to the department.
- (4) Owners of LOSS with design flows of 14,500 gpd or less shall employ one or more operators approved by a local health jurisdiction in Washington state.
- (5) If an operator described in WAC 246-272B-07200 (2) or (4) is unavailable, the owner of a LOSS shall propose and the department may accept a person with OSS or LOSS experience.
- (6) The operator shall prepare and sign monitoring reports, certifying that the results are correct and the report is complete, whether results are from process gauges or from an accredited laboratory.

[Statutory Authority: RCW 70.118B.020. WSR 11-12-035, \$ 246-272B-07200, filed 5/25/11, effective 7/1/11.]