

**WAC 296-304-02011 Warning signs and labels.** (1) Employee comprehension of signs and labels. You must ensure that each sign or label posted to comply with the requirements of this section is presented in a manner that can be perceived and understood by all employees.

(2) Posting of large work areas. A warning sign or label required by subsection (1) of this section need not be posted at an individual tank, compartment or work space within a work area if the entire work area has been tested and certified: "Not safe for workers," "not safe for hot work," and if the sign or label to this effect is posted conspicuously at each means of access to the work area.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-304-02011, filed 9/5/17, effective 10/6/17. Statutory Authority: Chapter 49.17 RCW. WSR 95-04-006, § 296-304-02011, filed 1/18/95, effective 3/10/95; Order 74-25, § 296-304-02011, filed 5/7/74.]