

**WAC 296-807-18040 Make sure abrasive wheels are safe to use.**

- (1) You must do the following before mounting a wheel:
  - (a) Visually inspect the wheel for cracks or damage;
  - (b) Perform a ring test for cracks (size and shape of the wheel permitting);
  - (c) Make sure the spindle speed of the machine is not greater than the operating speed of the wheel.
- (2) You must make sure a damaged or cracked wheel is not mounted or used.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-18040, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-18040, filed 4/4/03, effective 8/1/03.]