

**WAC 344-12-112 Agents to have access to all wells, well records, witness tests or well production.** All operators of oil and gas exploratory and producing wells are required to permit the agents of the supervisor and the committee to witness all tests that may be required by the supervisor on any and all wells. The agents of the supervisor shall have access to all well records, and shall be permitted to come upon any lease or property to inspect any and all wells and to witness gauging of production therefrom at all times. All such information, at the moment obtained, shall be presumed to have been required, filed, and requested to be kept confidential within the meaning of RCW 78.52.260, and shall by all such persons so obtaining such information, be reported only to the supervisor and the committee, and shall be kept confidential in the same manner as provided in RCW 78.52.260 and WAC 344-12-070(2).

[Statutory Authority: RCW 78.52.050. WSR 85-03-018 (Order 6, Resolution No. 10), § 344-12-112, filed 1/8/85. Statutory Authority: RCW 78.52.050 and chapter 78.52 RCW. WSR 82-12-052 (Order 3, Resolution No. 7), § 344-12-112, filed 6/1/82. Formerly WAC 344-12-120.]