

WAC 296-301-200 Dye kettles and vats. Pipes or drains of sufficient capacity to carry the contents safely away from the working area must be installed where there are dye kettles and vats which may at any time contain hot or corrosive liquids. These must not empty directly onto the floor.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-301-200, filed 9/5/17, effective 10/6/17; Order 74-19, § 296-301-200, filed 5/6/74.]