

WAC 296-807-17015 Lift the load safely. (1) You must place a block between the load cap and the load if the load could slip off the jack.

(2) You must secure the load from falling or slipping immediately after it is raised by one or more of the following:

- (a) Cribbing;
- (b) Blocking;
- (c) Some other equally effective method.

(3) You must make sure you do not exceed the limit of travel of the jack.

Note: The limit of travel can be determined by one or more of the following:

- 1. A positive stop;
- 2. A stop indicator;
- 3. Some other equally effective method.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-17015, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-17015, filed 4/4/03, effective 8/1/03.]