

WAC 296-806-20022 Keep power transmission equipment in good working condition. (1) You must make sure power transmission parts are kept in good working condition at **all** times.

(2) You must keep bearings free from lost motion and well lubricated.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-20022, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-20022, filed 6/29/04, effective 1/1/05.]