

WAC 296-807-18055 Make sure flanges are in good condition. (1)

You must make sure flange bearing surfaces are in good condition.

(2) You must replace or remachine any flange with a mounting surface that has any of the following problems:

- (a) Warped;
- (b) Burred on the bearing surface;
- (c) Excessively worn (thickness or diameter);
- (d) Out of true.

Note: Flanges that are refaced or trued need to satisfy minimum dimension requirements specified in ANSI B7.1-2000, Safety Requirements for the Use, Care and Protection of Abrasive Wheels.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050. WSR 15-23-086, § 296-807-18055, filed 11/17/15, effective 12/18/15. Statutory Authority: RCW 49.17.010, [49.17].040, [49.17].050, and [49.17].060. WSR 03-09-009, § 296-807-18055, filed 4/4/03, effective 8/1/03.]