- WAC 16-102-030 Permanent records. (1) A bound record book shall be provided for all permanent records.
- (2) All calibration results and check tests for initial calibration or subsequent calibration shall be recorded in permanent record book.
- (3) All tests for checking accuracy of calibration shall be recorded in permanent record book.

[Order 1133, \$16-102-030, filed 3/16/70.]