## WAC 296-803-400 Summary. Your responsibility:

To provide appropriate lockout and tagout devices and means to control energy.

You must meet the requirements	in this section:
Provide appropriate means to control energy	WAC 296-803-40005
Make sure lockout and tagout devices meet these requirements	WAC 296-803-40010
Make sure lockout devices meet these additional requirements	WAC 296-803-40015
Make sure tagout devices meet these additional requirements	WAC 296-803-40020

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-803-400, filed 9/5/17, effective 10/6/17; WSR 04-15-105, § 296-803-400, filed 7/20/04, effective 11/1/04.1