WAC 296-806-30032 Make sure shafting meets these requirements.

- (1) You must keep shafting free of:
- (a) Excessive oil or grease.
- (b) Rust or pitting from corrosion.
- (2) You must secure shafting against excessive endwise movement.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-30032, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-30032, filed 6/29/04, effective 1/1/05.]