WAC 296-863-30035 Make sure battery charging areas are safe.

- (1) You must make sure battery charging areas are designated and provided with all of the following:
 - (a) Means to flush and neutralize spilled electrolyte;
 - (b) Fire protection;
- (c) Ventilation that is adequate to disperse fumes from gassing batteries.
 - (2) You must prohibit smoking in battery charging areas.
- (3) You must take precautions to prevent open flames, sparks, or electric arcs in battery charging areas.
- (4) You must protect battery charging equipment from being damaged by PITs.
- (5) You must provide at least one of the following to handle batteries:
 - (a) Conveyor;
 - (b) Overhead hoist;
 - (c) Other equivalent material handling equipment.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-863-30035, filed 9/5/17, effective 10/6/17; WSR 04-19-051, § 296-863-30035, filed 9/14/04, effective 2/1/05.]