

WAC 296-835-110 General requirements. Summary.

Your responsibility:

Safeguard employees working with dip tanks.

You must meet the requirements...	in this section:
Construction	
Construct safe dip tanks	WAC 296-835-11005
Ventilation	
Provide proper ventilation for the vapor area	WAC 296-835-11010
Take additional precautions if you recirculate ventilation system exhaust air into the workplace	WAC 296-835-11015
Take additional precautions when using an exhaust hood	WAC 296-835-11020
Inspection	
Periodically inspect your dip tanks and associated equipment and correct any deficiencies	WAC 296-835-11025
First Aid	
Make sure employees working near dip tanks know appropriate first-aid procedures	WAC 296-835-11030
Cleaning	
Prepare dip tanks before cleaning	WAC 296-835-11035
Cyanide	
Safeguard cyanide tanks	WAC 296-835-11040
Welding	
Protect employees during welding, burning, or other work using open flames	WAC 296-835-11045
Liquid Harmful to Skin	
Protect employees that use liquids that may burn, irritate, or otherwise harm the skin	WAC 296-835-11050

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-835-110, filed 9/5/17, effective 10/6/17. Statutory Authority: RCW 49.17.010, [49.17].040, and [49.17].050. WSR 02-15-102, § 296-835-110, filed 7/17/02, effective 10/1/02.]