

WAC 173-130A-190 Bore hole information. It shall be the responsibility of the owner of all new or reworked wells drilled in the Odessa groundwater subarea to provide the department of ecology with such logs as the department may reasonably require.

[Statutory Authority: RCW 43.21A.060, 43.21A.080, 43.27A.090, 90.44.130 and 90.54.040(2). WSR 82-16-103 (Order DE 82-27), § 173-130A-190, filed 8/4/82. Formerly WAC 173-130-160.]