- WAC 296-843-14005 Establish site control. (1) You must maintain site work zones and site control as required by Table 1, Site Work Zone Requirements.
- (2) You must control access to the exclusion and contamination reduction zones.
- (3) You must make sure people wear personal protective equipment (PPE) appropriate to their work zone.

Table 1 Site Work Zone Requirements

For this type of work zone:	You must:
Exclusion zone	Establish entry and exit checkpoints on the zone's boundary
	Regulate the flow of people and equipment into and out of the zone
	Make sure exits go through a contamination reduction corridor
Contamination reduction zone with a contamination reduction corridor	Enter through a control point from the clean zone
	 Provide a transition or buffer between the exclusion zone and the clean zone
	 Perform all decontamination procedures
	Establish separate decontamination routes for people and equipment, if practical
	Remove all PPE worn in the contamination reduction or exclusion zones before entering the clean zone
Clean zone or support zone	Have no employee exposure to hazardous substances or health hazards

See Illustration 2 for an example of site work zones. Note:




Illustration 2 - Site Work Zones




Illustration 2a -Contamination Reduction Corridor

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 18-22-116, § 296-843-14005, filed 11/6/18, effective 12/7/18; WSR 04-02-053, § 296-843-14005, filed 1/5/04, effective 5/1/04.]