

WAC 296-835-110 General requirements. Summary.

Your responsibility:

Safeguard employees working with dip tanks.

| You must meet the requirements... | in this section: |
|--|-------------------------|
| Construction | |
| Construct safe dip tanks | WAC 296-835-11005 |
| Ventilation | |
| Provide proper ventilation for the vapor area | WAC 296-835-11010 |
| Take additional precautions if you recirculate ventilation system exhaust air into the workplace | WAC 296-835-11015 |
| Take additional precautions when using an exhaust hood | WAC 296-835-11020 |
| Inspection | |
| Periodically inspect your dip tanks and associated equipment and correct any deficiencies | WAC 296-835-11025 |
| First Aid | |
| Make sure employees working near dip tanks know appropriate first-aid procedures | WAC 296-835-11030 |
| Cleaning | |
| Prepare dip tanks before cleaning | WAC 296-835-11035 |
| Cyanide | |
| Safeguard cyanide tanks | WAC 296-835-11040 |
| Welding | |
| Protect employees during welding, burning, or other work using open flames | WAC 296-835-11045 |
| Liquid Harmful to Skin | |
| Protect employees that use liquids that may burn, irritate, or otherwise harm the skin | WAC 296-835-11050 |

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-835-110, filed 9/5/17, effective 10/6/17. Statutory Authority: RCW 49.17.010, [49.17].040, and [49.17].050. WSR 02-15-102, § 296-835-110, filed 7/17/02, effective 10/1/02.]