

WAC 296-36-035 General operating requirements—Safety miner.

(1) A safety miner shall be selected by the crew on each shift. He shall have at least five years' experience as a practical miner and shall be the holder of an unexpired first-aid certificate from the Red Cross, U.S. Bureau of Mines, or the department of labor and industries. His duties shall be to check conditions to eliminate common work hazards such as loose rock, faulty timbers, poor rails, insufficient lighting, defective ladders and scaffolds, fan pipes, firing lines and other equipment directly related to the work of a miner. If such defects are found he shall immediately report the same to the superintendent.

(2) It shall be the duty of the superintendent, upon ascertaining such defects or hazards, to take immediate steps to remedy the same in compliance with the rules hereinafter set forth. A record of inspections made on each operation shall be kept on file and a copy thereof shall be submitted to the safety division of the department of labor and industries.

(3) In the event that disagreement arises out of the interpretation of these rules, then the question shall be referred to the division of safety of the department of labor and industries for its decision in accordance with the laws of the state, the safety standards, or rules and regulations issued hereunder, and a decision thus rendered shall be binding.

[Rules (Part III B), filed 12/28/62; § 15, filed 3/23/60.]