

WAC 296-806-45010 Restrain extended workpieces on horizontal lathes. You must safeguard employees from the hazards of work pieces that extend beyond the edges of the horizontal lathe by:

- (1) Restraining work pieces as needed to prevent whipping; and
- (2) Isolating work pieces with an awareness barrier, fixed or movable guard, or railing.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-45010, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-45010, filed 6/29/04, effective 1/1/05.]