- WAC 246-243-070 Storage precautions. (1) Locked radiographic exposure devices and storage containers shall be physically secured to prevent tampering or removal by unauthorized personnel.
- (2) At least one calibrated and operable radiation survey instrument shall be available at the storage area whenever a radiographic exposure device, a storage container, or source is being placed in storage.

[Statutory Authority: RCW 70.98.050. WSR 94-01-073, § 246-243-070, filed 12/9/93, effective 1/9/94. Statutory Authority: RCW 43.70.040. WSR 91-02-049 (Order 121), recodified as § 246-243-070, filed 12/27/90, effective 1/31/91. Statutory Authority: RCW 70.98.050. WSR 81-01-011 (Order 1570), § 402-36-050, filed 12/8/80; Order 1084, § 402-36-050, filed 1/14/76; Order 1, § 402-36-050, filed 1/8/69; Rules (part), filed 10/26/66.]