- WAC 246-851-250 Minimum equipment requirements. (1) Licensed optometrists must have direct access on the premises to the following equipment and accessories, all of which must be in working condition:
  - (a) Adjustable examining chair;
  - (b) Phoropter/refractor;
  - (c) Retinoscope;
  - (d) Ophthalmoscope;
  - (e) Pupillary distance measuring device;
- (f) Projector and screen; or illuminated test cabinet, or chart for distant vision testing;
  - (q) Nearpoint vision testing equipment;
  - (h) Lensometer;
  - (i) Tonometer;
  - (j) Biomicroscope/slit lamp;
- (k) A clinically accepted visual field testing instrument or equipment.
- (2) Licensed optometrists who prescribe contact lenses must have direct access on the premises to the following equipment, all of which must be in working condition:
  - (a) Diameter gauge;
  - (b) Thickness gauge;
  - (c) Cobalt or black light instrument;
  - (d) Radiuscope/contactogauge type measuring instrument;
  - (e) Thickness tables;
- (f) Corneal measurement instrument that quantifies corneal curvature.

[Statutory Authority: RCW 18.54.070(2). WSR 02-10-065, § 246-851-250, filed 4/26/02, effective 5/27/02. Statutory Authority: RCW 18.54.070. WSR 91-06-025 (Order 119B), recodified as § 246-851-250, filed 2/26/91, effective 3/29/91; WSR 89-01-087 (Order 812), § 308-53-200, filed 12/21/88, effective 1/1/90; Order PL 256, § 308-53-200, filed 9/13/76.]