

WAC 480-90-338 Metering tolerance. A meter must not deviate more than two percent fast or slow at each test rate.

[Statutory Authority: RCW 80.01.040 and 80.04.160. WSR 01-11-003 (Docket No. UG-990294, General Order No. R-484), § 480-90-338, filed 5/3/01, effective 6/3/01.]